




# 100, 150





Przednia część płyty - brak okleiny PCV.  
The front part of the board - lack veneer PCV.






20	28	1	100-110
4	4	64	2
1	8	12	8
4			

Przednia część płyty - okelina PCV.  
The front part of the board - veneer PCV.

100, 150



0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 zmiierz przekatną



100, 150

